

RALLY TURKEY MARMARIS 2018



Date: 16.9.2018 **Time:** 16:45 hrs
Subject: STEWARDS DECISION NO. 5 **Document No:** 2.6

To: The Competitor ADAC SACHSEN E.V. of car No. 65
Crew JULIUS TANNERT / JÜRGEN HEIGL

The Stewards, having received a report from the Clerk of the Course with documentary evidence attached, summoned the above crew members as well as a competitor's representative, have considered the following matter and determine the following:

- Facts** Car 65 was driven in the opposite direction of the rally on SS 15 for approximately 30 meters.
- Offence** Article 20.1.4 of the 2018 FIA WRC Sporting Regulations
- Decision** No further action
- Reason** The driver and the co-driver appeared in front of the Stewards on 16.9.2018 at 15.45 hrs. The driver stated that the drive shaft of their car had broken immediately after the start of SS 15. As they were in the middle of an uphill, they could not proceed in the direction of the rally. At that location they would have been blocking the road for the following competitors. Therefore, they had turned the car around and had gone back downhill for approximately 30 meters. There they had waited for the next car to pass and then, with the help of marshals, moved the car few more meters to an even safer place.

The Stewards concluded that driving in the opposite direction of the rally was mandatory in order to clear the road.

The right to appeal this Decision is stipulated in the 2018 FIA International Sporting Code and in the 2018 FIA Judicial and Disciplinary Rules.

Timo Rautiainen
The Stewards

Surinder Thatthi

Ediz Atabey

Received by the above Competitor's representative:

Name (in block letters): TANNERT, JULIUS Date: 16.09.18

Position within the team: Driver Time: 17:15 hrs

Signature:

Published on the Official Notice Board on 16.9.2018 at 17:20 hrs